## DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

# WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-006938

Address: 333 Burma Road **Date Inspected:** 28-May-2009

City: Oakland, CA 94607

**OSM Arrival Time:** 645 **Project Name:** SAS Superstructure **OSM Departure Time:** 1845 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name:** Zhao Chen Sun **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A **Electrode to specification:** No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:** 

34-0006 **Bridge No: Component: OBG** components

## **Summary of Items Observed:**

On this date CALTRANS OSM Quality Assurance (QA) Inspector, Dilip Chakrabarti was present during the times noted above for observations relative to the work being performed.

Bay# 6-OBG Assembly

This QA Inspector randomly observed the following work in progress:

Magnetic Particle Testing (MT):

For Green Tag:

This QA inspector performed Magnetic Particle Testing (MT) of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated a TL-6028 MT report on this date.

The member and the weld designations are as follows:

Sl # Section # Weld # Green Tag # Location

1. BP 201-014 002.003 008494 10 C

2. SP 204-015 006,008,010,012 008495 10 C

3. DP 201-014 004,006,008 008496 11 B

Bay# 6-Tower Assembly

This QA Inspector randomly observed the following work in progress:

Magnetic Particle Testing (MT):

# WELDING INSPECTION REPORT

(Continued Page 2 of 3)

This QA inspector performed Magnetic Particle Testing (MT) of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated a TL-6028 MT report on this date. The member and the weld designations are as follows:

Sl # Section # Weld # Green Tag # Location

- 1. ESD1 DPSA4-4 B/B-4,5,12,13,20,21, NA NA
- 2. SSD1 DPSA4-5 B/B-6,7,16,17,22,25 NA NA

#### **SMAW Process:**

Welding of weld joints# B/B-8,9 located on PCMK ESD1 DPSA4-12. Welder is identified as 069493. ZPMC QC is identified as Zou Liu Hai. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-3312-TC-P5.

Welding of weld joints# B/B-12 located on PCMK WSD1 DPSA4-5. Welder is identified as 066459. ZPMC QC is identified as Zou Liu Hai. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-3312-TC-P5.

Welding of weld joints# B/B-23 located on PCMK ESD1 DPSA4-12. Welder is identified as 037779. ZPMC QC is identified as Zou Liu Hai. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-3312-TC-P5.

Welding of weld joints# B/B-13 located on PCMK WSD1 DPSA4-5. Welder is identified as 066481. ZPMC QC is identified as Zou Liu Hai. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-3312-TC-P5.

#### **SAW Process:**

Welding of weld joints# 1A located on PCMK NSD1 SA658-53M-14. Welder is identified as 054458. ZPMC QC is identified as Wang Xiao Bing. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-3221-TC-U5-S-1.

#### Bay # 7-OBG Assembly:

This QA Inspector randomly observed the following work in progress:

## FCAW Process:

Welding of weld joints# 3&4 located on PCMK SP 201-016. Welder is identified as 054459. ZPMC QC is identified as Zhong Chong Biao. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-2132-3.

Welding of weld joints# 11&12 located on PCMK SP 201-016. Welder is identified as 062447. ZPMC QC is identified as Zhong Chong Biao. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-2132-3.

Welding of weld joints# 7&8 located on PCMK SP 201-016. Welder is identified as 051246. ZPMC QC is

# WELDING INSPECTION REPORT

(Continued Page 3 of 3)

identified as Zhong Chong Biao. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-2132-3.

Unless otherwise noted, all work observed on this date appeared to be generally comply with applicable contract documents.

# **Summary of Conversations:**

No relevant conversations.

## **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 150-0042-2372, who represents the Office of Structural Materials for your project.

Inspected By:	Chakrabarti,Dilip Kumar	Quality Assurance Inspector
Reviewed By:	Clifford,William	QA Reviewer